



**COURROIES D'ENTRAÎNEMENT**  
**DRIVE BELT**  
**CORREA DE TRANSMISION**  
**TREIBRIEMEN**



16 Stries - Rasps - Estrias - Rippe

Longueur primitive Drive length Longitud correa Riemenlange	N°
1371	L15180
1397	L15181
1422	L15182
1562	L15183
1613	L15184
1664	L15185
1715	L15186
1764	L15187
1803	L15188
1841	L18189
1943	L15190
1981	L15191
2020	L15192
2070	L15193
2096	L15194
2134	L15195
2197	L15196
2235	L15197
2324	L15198
2362	L15199
2476	L15200
2515	L15201
2705	L15202
2743	L15203
2845	L15204
2895	L15205
2921	L15206
3086	L15207
3124	L15208
3289	L15209
3327	L15210
3492	L15211
3696	L15212
4051	L15213
4191	L15214



18 Stries - Rasps - Estrias - Rippe

Longueur primitive Drive length Longitud correa Riemenlange	N°
1075	2243711
1270	2243712
1397	2240921
1562	2243714
1613	2246911
1715	2240922
2020	2241023
2070	2241045
2197	2241024
2235	2241041
2362	2241025
2515	2241026
2705	2241027
2743	2246910
2845	2246917
3327	2241071



20 Stries - Rasps - Estrias - Rippe

Longueur primitive Drive length Longitud correa Riemenlange	N°
1841	L17726

9712104A

16.11.2004

**Tecnoma**  
 technologies

S.A.S. Capital 1174400€ - B.P. 195 - 51206 EPERNAY - FRANCE  
 Tel. (33) 26.51.99.99 - Télex : 830822 - Fax : (33) 26.51.83.51  
 R.C.S. EPERNAY B 350 484 309 - APE 293D

**1081.4**